

Look Filter Layers&Gos Netlist Selection Inspector Settings

Hierarchy Settings

Hierarchy Start Level

0

Hierarchy Stop Level

99

- ☒ Process Master Cells
- ☐ Process Terminal Cells
- ☒ Process Components

Rubbers

- ☐ Centric ☒ Barycentric ☐ Steiner

Layout Mode

- ☒ Symbolic (lambda) ☐ Real (foundry grid) ☐ nanometer ☐ micrometer